XYZ Airport Runway Safety Action Plan Month, Day, Year

On *Month/Day/Year*, the FAA Office of Runway Safety & Operational Services, Western-Pacific Region (AWP-1R), visited XYZ Airport. During the visit, the team met with airport and air traffic management for the purpose of generating a Runway Safety Action Plan (RSAP) for the airport.

Note: Please see the "Document Explanation and Response Procedure" link on the Runway Safety Program Page for a full explanation of action items, status, etc.

The following individuals were among those in attendance at the meetings:

List of attendees

The following is a list of new action items developed in cooperation with airport and air traffic management.

Action Item No: XYZ-05-001
Estimated Completion Date: 11/30/2007
Status: Open

Action Item: Recommend the airport develop a formal driver training program.

Remarks: Consider a multi-tiered program that would provide authorization to different

portions of the airport, i.e. specific ramp areas, hangar areas, runways, and taxiways. Also to be considered is a set of rules and regulations, with

Contact

consequences for non-compliance.

Update: 12/5/2005: Letter received from *Name* stating that the driver training program is

75% complete. It should be complete and implemented in 3 months.

Responsible Local Entity

XYZ Airport Manager Name

Note: Responsible Local Entity is the local person that one would go to as a

contact for this item.

Responsible FAA Regional Entity Contact

Airports Certification Inspector Name

Note: This is the regional representative from the FAA that should be contacted regarding questions/comments on this item.

Action Item No: XYZ-05-002
Estimated Completion Date: 1/30/2006
Status: Complete

DRAFT

XYZ Airport Runway Safety Action Plan

Action Item: Recommend the Local Runway Safety Action Team (LRSAT) determine the placement of a non-movement area marking throughout the airport as appropriate. Reference Advisory Circular (AC) 150-5340-1H. Any changes to the movement areas should be reflected in the Non-movement Area Letter of Agreement.

Responsible Local EntityContactXYZ Air Traffic ManagerName

Responsible FAA Regional EntityContactAirports Certification InspectorName

Action Item No: XYZ-05-003
Estimated Completion Date: 1/30/2006
Status: Closed

Action Item: Recommend the Airport construct an all weather service road connecting the south and north sides of the airport.

Responsible Local EntityContactXYZ Airport ManagerName

Responsible FAA Regional EntityContactAirports Certification InspectorName

Action Item No: XYZ-05-004
Estimated Completion Date: 1/30/2006
Status: Continuous

Action Item: Recommend the airport coordinate with Air Traffic and the ADO to conduct a

thorough line of sight study prior to any future construction of buildings on the

airport.

Responsible Local EntityContactXYZ Airport ManagerName

Responsible FAA Regional EntityContactAirports Certification InspectorName